

Table of Contents

- REF: Tools & Fasteners** 3
- General Drilling and Tapping** 3
- Drilling** 3
 - Use Sharp Drill Bits* 3
 - Grease or Oil the Bits* 4
 - Make a Pilot Hole Before Drilling* 4
- Tapping** 5
 - Thread Tolerance* 6
 - Removing a Broken Tap* 6
 - SAE and Metric Tap Drill Sizes* 6
- NPSC Tap Drill Sizes** 7
- Slotting Holes** 7

[Go To Technical Menu](#)

REF: Tools & Fasteners

General Drilling and Tapping

Drilling

Use Sharp Drill Bits

Always let the bit do the cutting.

Pressing harder on the drill only flexes the bit. (Broken bits or wallowed out holes to follow).

Just because a bit is new doesn't mean it is sharp or made for the application used on.

There may be quality control issues with a new bit at times that may have been already addressed by the tool maker.

But, not before you bought the bit.

Also, some bits are for general purpose usage and some are material specific.

Dull bits will still drill through most wood and burn through most plastics.

They will also work until they won't on steel and aluminum.

However, for a precision hole (for engine fasteners, helicoils and the like), it's best to make sure they are sharp.

- The longer the chips, the sharper the bit for the application.

This is an old bit going into a scrap piece of aircraft billet aluminum. The chips are too fine for a good cut. ¹⁾	These chips are broken into too small of pieces. ²⁾	These chips aren't great. But they're better than the previous ones. ³⁾
-------------------------------------------------------------------------------------------------------------------------------	----------------------------------------------------------------	------------------------------------------------------------------------------------



Grease or Oil the Bits

Make sure to cover drill bits, taps and dies in grease or heavy lube to capture any swarf (shavings) while working.

Back them out, clean and re-lube them periodically to minimize any loose particles getting loose in your work area.

This also helps to control heat buildup.

Lubing bits. ⁴⁾



Make a Pilot Hole Before Drilling

- A drill bit (without a pilot hole) will want to walk away from the originally intended starting place.
- A pilot (or center hole) is made with a center punch and a hammer and it establishes where the drill bit enters the piece to be drilled.

Center punch used to make a pilot hole for the drill bit. ⁵⁾



- **A pilot does not guarantee a straight hole** but rather just where the hole begins.

This hole was drilled starting off center, just a tad, although it looked centered before beginning. When the bit went down, it found the pilot hole and followed it even though it was not centered with the bit.

In the third pic below, it is obvious that the bit flexed to the pilot hole and began drilling in. When pulled out and back close to the hole, the offset is revealed.

This starts an off-centered hole and the bit will follow it to the end of the hole or until the bit flexes too far and binds up or breaks. ⁶⁾



- While using a drill press, watch the end of the bit when first engaging the pilot hole. If the bit flexes to the pilot when spinning, it can be noticed before the hole is fully started and you can adjust the piece to the bit center from there. (before plunging into the hole)
- While using a hand drill, the bit will find the pilot center and follow it though at whatever angle the drill is.



Tapping

Make sure to use sharp tap and dies. ¹¹⁾

Thread Tolerance

Threads can be cut to a tighter or looser fit depending on the needs or sometimes availability of drill bit sizes. For instance, drill bits are available in a wide variety of sets or kits. The most common sizes are usually the ones that are provided. However, many suppliers carry a drill index kit which comes with a huge amount of drill bits in step sizes. Some are in 1/32 steps and some are in one thousandths increments. So, if you want a close tolerance fit on a 3/8"x16 threaded connection, you could use a 0.2969" pre-drill or for a looser fit you could use a 0.3230" pre-drill. Even with a standard 0.3125" drill bit, a hand drill is not going to produce a straight hole every time. If you have to over compensate with it and wallow out the hole just a bit to get it straight, you may be producing a looser threaded connection without realizing it. Care should be taken on tighter pre-drilled holes since it creates more friction and heat when tapping than a standard or slightly larger hole and it can lead to breaking taps off in the hole or cracking the piece you're working on. ¹²⁾

Removing a Broken Tap

- The best way to remove a broken carbon steel tap is to use a small hole punch to the center of the broken tap and smack it with a hammer while exploding the hardened tap. You don't stand a chance at drilling it out without damaging the hole/ threads and chances are since pressure was enough to break the tap, it'll take more pressure than that to remove the broken lil stubby that's left. ^{13) 14)}

SAE and Metric Tap Drill Sizes

Below are standard pre-drill sizes for size taps used. These are common drill sizes and they are sufficient for most applications on a Sportster. ¹⁵⁾


SAE Tap	Drill Size	Drill Bit	Metric Tap	Drill Bit
Thread size	#/Letter	Diameter- in	Thread Size	Diameter- mm / in
6×32	36	0.1065"	M3 x 0.5	2.50 mm / 0.0984"
#6×40	33	0.1130"	M3.5 x 0.6	2.90 mm / 0.1142"
#8×32 #8-36	29	0.1360"	M4 x 0.7	3.30 mm / 0.1299"
#10×24	25	0.1495"	M4.5 x 0.75	3.70 mm / 0.1457"
#10×32	21	0.1590"	M5 x 0.8	4.20 mm / 0.1654"
#12×24	16	0.1770"	M6 x 1	5.00 mm / 0.1968"
#12×28	14	0.1820"	M7 x 1	6.00 mm / 0.2362"
1/4"×20	7	0.2010"	M8 x 1.25	6.70 mm / 0.2638"
1/4"×28	3	0.2130"	M8 x 1	7.00 mm / 0.2756"
5/16"×18	F	0.2570"	M10 x 1.5	8.50 mm / 0.3346"

SAE Tap	Drill Size	Drill Bit	Metric Tap	Drill Bit
Thread size	#/Letter	Diameter- in	Thread Size	Diameter- mm / in
5/16"x24	I	0.2720"	M10 x 1.25	8.70 mm / 0.3425"
3/8"x16	5/16	0.3125"	M12 x 1.75	10.20 mm / 0.4016"
3/8"x24	Q	0.3320"	M12 x 1.25	10.80 mm / 0.4252"
7/16"x14	U	0.3680"	M14 x 2	12.00 mm / 0.4724"
7/16"x20	25/64	0.3906"	M14 x 1.5	12.50 mm / 0.4921"
1/2"x13	27/64	0.4219"	M16 x 2	14.00 mm / 0.5512"
1/2"x20	29/64	0.4531"	M16 x 1.5	14.50 mm / 0.5709"
9/16"x12	31/64	0.4844"	M18 x 2.5	15.50 mm / 0.6102"
9/16"x18	33/64	0.5156"	M18 x 1.5	16.50 mm / 0.6496"
5/8"x11	17/32	0.5312"	M20 x 2.5	17.50 mm / 0.6890"
5/8"x18	37/64	0.5781"	M20 x 1.5	18.50 mm / 0.7283"
3/4"x10	21/32	0.6562"		
3/4"x16	11/16	0.6875"		
7/8"x9	49/64	0.7656"		
7/8"x14	13/16"	0.8125"		
1"x8	7/8"	0.8750"		
1"x12	59/64"	0.9219"		
1"x14	15/16	0.9375"		


NPSC Tap Drill Sizes

Tap / Thread Size	Drill Size ¹⁶⁾
1/8-27	11/32
1/4-18	7/16
3/8-18	37/64
1/2-14	23/32
3/4-14	59/64

Slotting Holes



Scribing cut marks in the material will help keep the cut straight when hand grinding.
 Drilling the end of the new slot and grinding left over edges works well also.



17)

Go To Technical Menu

1) 2) 3) 7) 8) 9) 10)

photo by Hippysmack

4)

photos by sifty of the XLFORUM

<https://www.xlforum.net/forum/sportster-motorcycle-forum/sportster-motorcycle-era-specific-and-model-specific/ironhead-sportster-motorcycle-talk-1957-1985/146604-first-harley-1975-xl1000-caf%C3%A9-project/page5?t=1592463&page=5>

5) 6)

photos by Hippysmack

11)

Shadowdog500 of the XLFORUM

<https://www.xlforum.net/forum/sportster-motorcycle-forum/sportster-motorcycle-era-specific-and-model-specific/ironhead-sportster-motorcycle-talk-1957-1985/51523-question-about-my-rocker-oil-lines?t=221093&highlight=split+rocker+box>

12)

hippysmack from the XLFORUM

13)

hippysmack

14)

Article by Oldrump1

<https://www.xlforum.net/forum/sportster-motorcycle-forum/sportster-motorcycle-general-discussion-and-problems/181908-assembly-prep?t=1959533>

15)

Starrett tap drill sizes chart unless otherwise noted

16)

Starrett tap drill sizes chart

17)

drawing by Hippysmack

From:
<http://sportsterpedia.com/> - **Sportsterpedia**

Permanent link:
<http://sportsterpedia.com/doku.php/techtalk:ref:tools030>

Last update: **2023/12/20 16:33**

