



GENUINE MOTOR PARTS AND MOTOR ACCESSORIES BULLETIN

P&A NO. 1035

DATE: 2/3/2015



Sportster Side Cover Clip Improvement

We have found a tolerance issue between the mating clips found in kits 70416-04D and 70417-04C used on Sportster side covers. As a result, we have modified the parts to improve the fit between the clips.

Required Dealer Action:

1. Scrap the 70416-04D and 70417-04C kits you have in stock if the package date is prior to 01/04/2015
2. Re-order more if needed.
3. Please file a Defective Stock request (DFS) to gain credit for the stock you scrap using the chart below

ITEM	DETAILS
Claim Type	DFS
Problem Part No.	70416-04D and/or 70417-04C
Quantity	Varies depending on inventory
Customer Concern Code	9203
Condition Code	9110
Note: Enter PAB1035 in Event Comments	
Note: Do not use a VIN when submitting claim	

Questions

Please contact Technical Service with any concerns regarding application. Please direct all other questions to your Dealer Services Representative.

