Digital Technician Phase 8 DVD Update

Installation of Phase 8 DVD

If you insert the DVD to install Phase 8 and nothing happens, its most likely caused by the DVD not snapping in properly on the spindle. This is easily fixed by reinserting the DVD in the Drive. When resetting DVD on spindle, press down around the spindle area until DVD inserts under the 3 spindle springs. Then try spinning the DVD with you finger to ensure it spins without wobbling.

Phase 8 requires reprogramming Techlink software

You will automatically get a prompt to update Techlink the first time you connect to a motorcycle.

Procedure: Enter motorcycle VIN (or select Year/Make/Model/Region/Odometer). The Auto-Detect button will not work the first time but will after Techlink software is reprogrammed. Once you enter motorcycle information and click the green checkmark follow the on-screen prompts to reprogram Techlink.

Length of Record time shortened

Recording of live data is still done the same way but after you press the red circle Record button (at the bottom of the Data Item screen) the maximum recording time is now only 1 minute. In a future update the length of recording time will be extended.