

February 2, 2004

1998-2002 Radio Upgrade

The supply of Ultra circuit boards used by RSI for upgrading radios has been depleted so upgrades on 1998-2002 radios are no longer possible. 2003 and later radios were never upgradable. This means that the only way to upgrade a 1998 and later motorcycle to Ultra configuration is to purchase a -04 radio. Refer to Radio and CD Player Upgrades in the Genuine Motor Accessories catalog.

2004 ECM Calibrations

Be certain to install the proper ECM calibration download. The speedometer and check engine light circuits are activated differently on 2004 models so installing an earlier calibration will result in code P1651 and erroneous speedometer readings. Refer to Tech Tips for the latest calibration information.