## **FXDSE Fork Lock Operation**

We have recently seen an increase in cosmetic damage to the lower triple tree on CVO FXDSE models as a result of improper use of the fork lock.

The front wheel must be turned all the way to the left *before* the ignition switch is turned to the fork lock position.

If the key is turned to fork lock position first, damage to the lower triple tree and fork locking pin will result when the forks are turned. This is because the lower triple tree allows the fork locking pin to fall down when the key is turned and the wheel is facing forward.

Please explain the correct operation to your customer's. Damage as a result of improper use is not warrantable.