



HARLEY-DAVIDSON

PARTS & ACCESSORIES BULLETIN

May 29, 1982

P&A 182

NEW 4-PAK OIL CARRIER P/N 99512-77

Up until now the 4-pak oil carrier was supplied to dealers free of charge. Several cost increases, however, make this prohibitive, and regrettably we must now charge a minimum price of \$.20 each.

We have also changed the design to the new corporate Bar & Shield logo and colors; and the package quantity has been increased from 15 to 25.

<u>Part No.</u>	<u>Name</u>	<u>Pkg. Qty.</u>	<u>Net</u>
99512-77	4-Pak Oil Carrier	25	\$.20 ea.

It will be necessary to re-order these new carriers, since all backorders for the old design, free carriers are being cancelled.

REPLACEMENT FOR

7 IN. HALOGEN HEADLIGHT SEALED UNIT P/N 67755-79

This sealed unit is no longer available and backorders for this part are being cancelled.

A replacement is available, but it is not a sealed unit. The new headlamp is a composite unit, and the headlamp and bulb must be ordered separately, as follows:

<u>Part No.</u>	<u>Name</u>	<u>Pkg. Qty.</u>	<u>Net</u>	<u>List</u>
67755-81	Headlamp (less bulb)		\$16.80	\$28.05
67697-81	Bulb	4	\$ 6.97	\$13.95

An order blank is attached for you to re-order to meet your requirements.

HARLEY-DAVIDSON MOTOR CO., INC.
P.O. BOX 594 MILWAUKEE, WIS., U.S.A. 53201
PARTS AND ACCESSORY ORDER

May 29, 1982

P & A 182

TYPE CODE	ORDER TYPE	VEHICLE IDENTIFICATION NUMBER
R	REGULAR	
P	POLICE	
D	DOWN VEHICLE	
W	WARRANTY	

DEALER ORDER
ORDER DATE
DEALER NO
ORDER TYPE
WARRANTY CLAIM NO

FOR OFFICE USE ONLY

ACCT.	
FRT ACCT	

S O L D	NAME
	ADDRESS
	CITY/STATE/ZIP

S
H
I
P

NAME _____

ADDRESS _____

CITY/STATE/ZIP _____

[illegible]

PLEASE USE PART NUMBERS
DO NOT USE FOR
CORRESPONDENCE

[illegible]

PLEASE USE PART NUMBERS
DO NOT USE FOR
CORRESPONDENCE

PRINTED
IN U.S.A.