



HARLEY-DAVIDSON

PARTS & ACCESSORIES BULLETIN

December 6, 1983

P&A 210A

BULLETIN ERROR - PLEASE READ IMMEDIATELY

This bulletin supercedes P&A 210 dated November 29, 1983, which incorrectly described P/N 37311-75A as a Clutch Release Bearing. IT SHOULD HAVE BEEN DESCRIBED AS A THRUST WASHER, INNER. The corrected bulletin reads as follows:

THRUST WASHER, INNER
P/N 37311-75A

It has been brought to our attention that a bad shipment of P/N 37311-75A, Thrust Washer, Inner was received by the Parts & Accessories Division and shipped to many dealers between June 15, 1983 and November 1, 1983. Please check your stock of Thrust Washers and discard any inventory you may have that has a date stamp on the package between June 15 - November 1, 1983. The date stamp will appear on the package as a date either right below or next to the part number. Please file an E-Form for the quantity of parts you have to discard. If is not necessary to return the bad parts. We will verify any discrepancies against our parts shipment records to each dealer.

Please discard P&A Bulletin 210 and replace it with this corrected copy We are extremely sorry for any inconvenience this may have caused.

dmg