

PARTS & ACCESSORIES BULLETIN MAY 10, 1985 P&A +247

V² EVOLUTIONTM TAPPET CHANGE AFFECTS

SCREAMIN'EAGLE SOLID LIFTER KIT

The V^2 EvolutionTM engine has a new style valve tappet. The tappet (P/N 18522-85) started into engine production in April beginning with crankcase set #1585 093 013. While it interchanges with the earlier unit (P/N 18522-83), the new tappet will not accept the Screamin'Eagle Solid Lifter Kit (P/N 18500-84) due to differences in internal design. DO NOT attempt to use the Solid Lifter Kit with these new tappet assemblies.

A new Solid Lifter Kit is now on test and will be available soon. In the interim, keep in mind that the Cam and Spring Kit $(P/N\ 25490-84)$ was designed for use with hydraulic or solid lifters and may be run successfully either way.

AVAILABLE NOW 1985 MODEL OWNER'S MAINTENANCE GUIDE

PART No. 99952-85

THIS BOOK COVERS THE ESSENTIALS OF RIDER MAINTENANCE WITH EASILY UNDERSTOOD STEP-BY-STEP ILLUSTRATED INSTRUCTIONS.

EMPHASIZES DEALERSHIP SERVICE FOR NON-ROUTINE MAINTENANCE.

Illustrations, Photographs, & Diagrams
On All 1985 Models.

Nominal Dealer Cost - \$ 5.00.

A HANDY REFERENCE FOR EVERY RIDER'S TOUR PAK OR SADDLEBAG.

FEATURED IN ENTHUSIAST MAGAZINE.

AVAILABLE NOW - SAMPLE COPY SHIPPED IN APRIL.

ORDER ADDITIONAL COPIES THROUGH
P&A DIVISION - PART NUMBER 99952-85.