# **Warranty Information**

Please be sure the warranty administration people in your dealership get a copy of the following information.

It has been brought to our attention that corrections to the 2002 & 2003 models listed below are necessary for the following labor codes:

```
7882 — Code 35-Tach — time has been changed to 0.7 hrs
7883 — Code 35-Tach — time has been changed to 0.4 hrs
7886 — Tachometer — time has been changed to 0.6 hrs
```

## Model Year 2002 VIN's

FLHTCIF	FW.
FLHTCUI F	-CW
FLHTCUI W/SC F	-GW
FLTRI F	-SW
FLHRIF	-BW
FLHRCI F	FRW
FLHTCUI Shrine F	
FLHRI ShrineF	=WW
FLHTPIF	-MW
FLHPI F	-HW
FLHPEI (Calif.+ Japan Only) F	-TW

## Model Year 2003 VIN's

FLHTI	FVW
FLHTCI	FFW
FLHTCI Anniversary	FFW
FLHTCUI	FCW
FLHTCUI Anniversary	FCW
FLHTCUI W/SC	
FLHTCUI W/SC Anniversary	FGW
FLTRI	FSW
FLHRI	FBW
FLHRCI	FRW
FLHTCI Shrine	FKW
FLHTCUI Shrine	FLW
FLHRI Shrine	FWW
FLHTPI	FMW
FLHPI	FHW
FLHPEI (Calif.+ Japan Only)	FTW

# 2002 & 2003 Dyna Flat Rate Corrections

There was a mis-print in the flat rate manuals as follows:

## **Code 35-Tachometer Error**

# 2002 - Dyna

Page 5-29, code 7885 needs to be changed to 7886 (time of 0.5 remains the same). Page 6-12, code 7885 needs to be changed to 7886 (time of 0.5 remains the same).

## 2003 - Dyna

Page 5-30, code 7885 needs to be changed to 7886 (time of 0.5 remains the same). Page 6-13, code 7885 needs to be changed to 7886 (time of 0.5 remains the same).

# **VRSCA Model (Wheels)**

Labor code 2106 and 2111 for the 2002 and 2003 VRSCA (HAZ) model has been increased from 0.6 hours to 0.9 hours.

Please document corrections in your 2002 and 2003 job/time code manuals in the appropriate model sections.

#### **New Condition Codes**

## **Switches**

R/R H/ Bar Cruise Set Switch	. 5182
R/R H/ Bar Function Switch	. 5183
R/R H/ Bar Ptt Switch	. 5184

The new condition codes are now available on H-Dnet.com under the Service tab.

## **Warranty Best Practices**

Please have your dealer number and claim number available when calling Warranty/SPOC at

1-800-664- Also, be prepared to provide the vehicle's identification number, owner's name, and the original date of purchase on all VIN related claims.

When faxing recall order forms, please fax to 414-343- . Do not rightfax.