



# TT462: SHIPPING KEYS CABLE STRAPS

2019-09-20



Other  
Category

APPLIES TO	SYMPTOMS
All vehicle platforms	• PDI (Predelivery Inspection)

## Reason for Revision

Refer to Table 1.

**Table 1. Document History**

Date	Revision Description
2017-11-14	Initial release
2018-06-12	Bulletin title update
	* Updated <b>Title</b>
2019-09-20	Quick release cable strap
	* Updated Reason for Technical Tip Bulletin, Tear-Away Cable Strap, Video
	* Added Resolution : Quick Release Cable Strap, Resolution : Figure 2

## Reason for Technical Tip Bulletin

The assembly plants are implementing a **new** cable strap.

## Motorcycles Affected

All vehicle platforms.

## Markets Affected

All markets are affected.

## Issue

Damage has occurred on some hand grips or brake levers when using side cutters to cut the cable strap that holds the keys in place.

## Resolution

### Tear-Away Cable Strap

1. See Figure 1. Remove tear-away cable strap.
  - a. Grasp tail (1) of cable strap with one hand.
  - b. Grasp tear-away tab (2) with other hand.

- c. Pull tab to release. Refer to Video.

## Quick Release Cable Strap

1. See Figure 2. Remove quick release cable strap.
  - a. Put finger nail between the tip (2) and the release tab (3) in the head (1).
  - b. Pull release tab away from the tip.
  - c. Remove tip from head.
  - d. Remove cable strap from vehicle. Refer to Video.


## Video

### NOTE


*Login into SIP (Service Information Portal) through Google Chrome to view video.*

Click on link to view video of the removal of the cable strap.

- Tear-Away Cable Strap Video
- Quick Release Cable Strap Video



**Figure 1. Tear-Away Cable Strap**



- 1. Head
- 2. Tip

- 3. Release tab

**Figure 2. Quick Release Cable Strap**