



GENUINE MOTOR PARTS AND MOTOR ACCESSORIES BULLETIN



PAB1068

2017-09-15

PAB1068: SCREAMIN' EAGLE TUNER CALIBRATION DELAY FOR SELECT 2018 CVO MODELS

Purpose of P&A Bulletin

To notify dealers that base calibrations are temporarily unavailable for Screamin' Eagle® Stage II, III and IV upgrades for select 2018 CVO™ models.

Summary

The base calibrations listed below for Screamin' Eagle Stage II, III, IV upgrades are currently unavailable in the Screamin' Eagle Pro Street Tuner and the Super Tuner Pro software. Software updates containing the new calibrations are expected to release November 2017.

Calibrations Delayed:

2018 FLHTKSE:

- 117ci Stage II POWER – Twin Cooled™

NOTE

Screamin' Eagle will not release 117ci Stage II TORQUE calibrations due to similar performance to the 117ci OE (Original equipment) configuration.

2018 FLHXSE and FLTRXSE:

- 117ci Stage II POWER – Oil Cooled

NOTE

Screamin' Eagle will not release 117ci Stage II TORQUE calibrations due to similar performance to the 117ci OE configuration.

- 117ci to 117ci Stage III – Oil Cooled
- 117ci to 117ci Stage IV – Oil Cooled

Questions

Contact Technical Service with any concerns regarding this application. Direct all other questions to a Dealer Services Representative.

Draft

